

Malcolm Soft OS support table(2023/03 Update)

No	Product name	Model	Latest Ver.*2	Status	OS					Notice
					Windows 7		Windows 10		Windows 11	
					32Bit	64Bit	32Bit	64Bit	64Bit	
1	Viscosity Evaluation Program for Spiral Viscometer	VAM-2	2.13	Discontinued	△	△	—	—	—	
2		VAM-3	3.0.3.0	Discontinued	○	△	○	△	△	
3		VAM-5	v1.2.1.0		○	○	○	○	○	
4	Software for SP-2	SPIN-2	3.24		○	○	○	○	○	※You need to change the screen resolution setting.
5	TEMPERATURE ANALYSIS PROGRAM	TAM-16	1.11	Discontinued	△	△	—	—	—	
6		TAM-4	3.43	Discontinued	△	×	—	—	—	
7		TAM-50	3.19	Discontinued	○	△	—	—	—	
8		TAM-60	1.18		○	○	○	○	○	
9		TAM-6	1.25	Discontinued	○	△	○	△	△	
10		TAM-4IRC	3.16	Discontinued	○	△	○	△	△	
11	Total Monitoring for Reflow Process TMR System Program	TMR-1	2.12		?	?	?	○	○	
12	Software for ECL-2	ECL-S	3.05	Discontinued	△	×	—	—	—	
13	REFLOW SIMULATOR CONTROL PROGRAM	SRS-1CS	1.32		○	○	○	○	○	
14	Reflow Profile Analysis Program	RDT-250S	1.301		○	○	○	○	○	
15	Software for STAP-2	STAP-2	2.456		△	△	○	○	○	
16	Software for Tackiness Tester	TKW-2	1.01		○	○	○	○	○	
17	Compact Reflow Oven Software	RDT-165CS	1.00		△	×	△	△	?	※You need to change the screen resolution setting.
18	Dip Wetting Tester Analysis Program	SWB-S2	1.36		○	○	○	○	○	
19	Protocol management software	PNE Sequence	3.10		△	×	?	?	?	
20	Software for SPS_2000	SPS-2000S	1.03		○	×	?	?	?	
21	REFLOW SIMULATOR CONTROL PROGRAM	SRS-S	3.00	Discontinued	○	○	○	○	○	
22	eSPECT		1.67	Discontinued	○	○	○	○	○	
23	ES-tab		1.00	Discontinued	○	○	○	○	△	
24	PCU-02V Controller		1.0.1.0		—	○	○	○	○	
25	Software for dip tester	DS-10	1.07		○	△	○	○	○	
26	Software for dip tester	DS-10S	1.07		○	△	○	○	○	
27	VIDEO CAMERA CAPTURE SYSTEM	VDM-3	1.1.4.1		—	—	—	○	○	
28		VDM-3Player	1.1.1.1		○	△	○	○	○	

- Support
- △ You may need to run the program in administrator mode. Also, it is not guaranteed to work in all environments.
- ? Operation not yet confirmed
- ×
- Not support
- Not support